

		Woore Parish Council Fix My Street Log (Update 06.03.23)				
Date Reported	Status	Location	Description	Date Fixed	Notes	Shropshire Council Ref.
11/08/2021		A525 W/B carriageway, opposite the Property known as "The Brambles"	Rocking manhole cover, in danger of collapse.Severn Trent		This cover has previously had the blacktop surrounding it replaced, however the cover was not replaced at the same time!Previously reported to Shropshire Council some 3 months previously. - <b>Updated on FMS 29.09.21- no action</b>	
19/08/2021		A51 in the middle of S/B Lane	Linear pothole, road surface breaking up over approx. 10m length. Previously patched. Also breaking up around MH in carriageway channel.	<b>W/C12.09.22 Partial Fix Only</b>	Previously reported to Shropshire Council some <b>3 and 6 months</b> previously. Some white paint on carriageway. <b>Update on FMS 16.01.22 -This Pothole is now a significant danger, and is now 150mm deep and presents a significant hazard to the travelling public, and requires immediate attention. It is now over 9 months since this was first</b>	
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Faircross	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway <b>Update on FMS 07.03.21-This gully is on the verge of structural failure, the surround has been completely eroded, and the frame is clanking. It is compounded by the fact that the lane is now been trafficked as a single lane under traffic lights, because of Western Power's works, thus doubling the traffic on it and it will collapse any day! requires</b> New Report. Updated on FMS 04.10.21. <b>No Action as at 06.11.21 reported on FMS.</b>	
06/09/2021		Overgrown Hedge leading to Public Footpath 0236/23/1 at end of Northlands Woore	Hedge needs cutting back		<b>No Action - Updated on FMS 29.10.21 as no action</b>	
30/09/2021		A51 Verge - Steps and Handrail Leading up to Public Footpath 0236/26/1	Steps and handrail in need of repair since the handrail has rotted and steps eroded.		<b>No Action - Update posted on FMS 29.10.21 still no action</b>	
30/09/2021		B5026 Bearstone Road entrance	Loose Public Footpath (0236/33/1) Sign, needs re-affixing to Stile.		<b>New Report. Updated on FMS 29.10.21 - No Action Update on FMS 27.10.22 Still no resolution on this issue.</b>	
29/10/2021		Several Potholes on Dorrington Lane, Woore	Several potholes been here for months have to nearly go into stream to avoid. Between The white House and the westlands. Dorrington Lane near woore		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
06/10/2021		A51 S/B carriageway opposite junction with Bearstone Road.	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		New Report <b>No Action as at 06.11.21 reported on FMS</b>	
07/10/2021		Eastern end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report <b>No Action as at 06.11.21 reported on FMS</b>	
07/10/2021		Middle of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report <b>No Action as at 06.11.21 reported on FMS</b>	
07/10/2021		A525 Edge of E/B carriageway approx. 40m past junction with Beech Avenue	Edge of carriageway breaking up and has developed into a serious linear pothole approx 100x500x100 deep, adjacent to previous repair. Dangerous for cyclists and cars.		New Report <b>No Action as at 06.11.21 reported on FMS 10.12.21 - The deficit as reported has been patched, although other adjacent areas remain unprepared.</b>	
07/10/2021		Public Footpath 236/47/1 through Woore Church Yard	Deterioration of footpath through churchyard is a hazard for pedestrians and need repair. First reported. 10.04.21. Outdoor Recreation gave Ref. No. UM110821:90a81 Route No:0236/47/1		New Report First Reported to SC on 19.04.21	UM110821:90a81
07/10/2021		Public Footpath 0236/23/21 at the entrance from Northlands	Footpath has deteriorated at the entrance to Northlands and is presenting a trip hazard. Outdoor recreation advised the following ref. No. UM110821:1a5c7 Route No: 0236/23/1		New Report First Reported to SC on 11.08.21	UM110821:1a5c7
19/10/2021		Intersection of Public Footpaths 0236/22/1 and 236/23/1on Eastern Boundary of Fields behind Northlands.	Post requires replacement of Field gate on Footpath 0236/23/1		New Report	
21/10/2021		B5025 Dorrington Lane and Watery Lane Crossroads	At Dorrington lane end where the 5026 leads to Irelands Cross, the constant flooding has still not been addressed and this morning, where most other flood prone sites are clear of water, this junction has a pool 2/3rds of the way across the B Road and round the corner adjacent. Our understanding is that this constantly floods due to the water running down Dorrington Lane out of the ditch and down onto the B5026. The drains are silted up and can't cope with all the water.		New Report - First reported to SC several months ago.	SR-174964-T9K7D9
21/10/2021		Severe Flooding on Bearstone Road	Bearstone Road flooding – issue is broken pipes – SC have visited site and instructed SC drainage works team to perform repairs – 3 month notice required for road closure - awaiting update.		New Report - First reported to SC several months ago. Update <b>10.12.21</b> - Shropshire Council advised that their contractor has attended site to deal with this, but couldn't do anything because of the flooding! They are to write again to adjacent landowners ref Ditch cleaning.	
21/10/2021		A525/A51 Junction, Audlem Side.	Badly deteriorated road surface, and erased stop line. Vehicles are encroaching into the A51 carriageway to gain visibility around parked cars in lay-by. The absence of the sop line is very dangerous since there is no guide to the driver to stop. Eroded road surface is danger for vehicles under heavy braking with flooded potholes and the risk of ice forming with the onset on winter.	<b>White lines renewed on an unmatched surface, therefore not complete 08/22</b>	New Report	

21/10/2021	Blocked foot way gully on A525 adjacent to Woore Post Office	Drainage gully at the back of the footpath is blocked, and or possibly the outfall drain. Water is discharging across the footpath, and is causing a dangerous surface for pedestrians. This will be exacerbated by the onset of frosty weather causing ice formation with the associated hazards.		New Report - SC attended site on 12.11.21 and attempted to clear the blockage in the outfall drain. The operatives reported to Andy Morris in Woore Country Stores, they thought that the drain was collapsed as a result of excavation work carried out by ST to install a new meter, since there is new surfacing over the area of the drain. They have referred the matter back to the SC Drainage engineers for resolution.	SR-175797-P3B4L6
16/03/2022	Street. Lamp No 38 on the A51 at Crossways	Street Lamp is continuously illuminated		<b>New Report - Reported by resident on Shropshire portal.</b> <b>Now reported on FMS 25.03.22.</b> <b>Update on FMS 27.10.22 Lamp still burning continuously as it has been for the last 7 months.</b> <b>Updated on FMS 06.03.23 - There is an intermittent fault on the Street Lighting circuit from Irelands Cross Junction with the B6026 to Phoenix Rise, whereby there are various lamps which are burning continuously on this section of road. It may be due to an underground cable fault?</b>	14085487
19/03/2022	Footpath Post opposite Bankfoot in Gravenhunger Lane Woore	Post is rooted and snapped off, requires replacement, lying against the hedge.		<b>New Report on FMS 19.03.22</b>	
25/03/2022	Rocking Gully Grid on the A51 Opposite Phenix Rise Pipe Gate.	Gully grating is loose as road surface has collapsed around it. Dangerous to all passing traffic, danger of collapse.		<b>New Report on FMS 25.03.22</b>	
06/04/2022	Gateway and signage Gravenhunger Lane Woore	These signs are looking dilapidated, and overgrown. It needs the vegetation and bushes cutting back, and the signage refurbishing or replacing. This is a very well used pedestrian route, and the signage is there to warn motorists of the speed limit and presence of pedestrians. It was installed by SC as part of the quiet lanes initiative.		<b>New Report on FMS 06.04.22</b>	
08.05.22	A525 Audlem Road on Westbound side of C/way	This manhole has previously had the surround to the ironwork replaced, but is now breaking up again, and there are two significant potholes appearing.		<b>New Report on FMS 08.05.22</b>	
08.05.22	Collapsed gully grid on A51 S/B opposite new Development of two Houses.	Gully grid has subsided by about 100mm, and is in danger of collapse. C/way is sub-standard width and receives full HGV loading in the channel, requires immediate attention.		<b>New Report on FMS 08.05.22</b>	
16.07.22	Demolished bollard on junction of A51 and A5026 at Irelands Cross	Centre Island Bollard has been demolished by vehicular traffic, yet again! The island needs to be re-engineered to allow the passage of large articulated HGV's and large farm tractors towing very large trailers.		<b>New Report on FMS 16.05.22</b>	
17.07.22	40mph repeater sign by Holy Cottage on the A51 S/B	Sign obscured by the hedge.		<b>New Report on FMS 17.07.22</b>	
22.07.22	A51 Adjacent To Flash Farm House	The gullies and the culvert under the A51 to the outfall are blocked with debris. As a result under heavy rainfall the carriageway floods and drains into Flash Farm House, which is lower than the carriageway. This issue has been flagged with SC over a year ago, but no action has been taken, and the situation has only got worse. The property has suffered flood damage on several occasions as a result of this cyclic		<b>New Report on FMS 22.07.22 (reported on SC Highways Portal in April 2021)</b>	
25.07.22	Public ROW sign on Gravenhunger Lane Wooreby Aston Hall	PORW sign destroyed by hedge cutting operation.		<b>New Report on FMS 25.07.22</b>	
30.07.22	Public ROW 0236/26/1 adjacent to Phoenix Rise Development	The ROW 0236/26/1 which runs behind the Phoenix Rise Development is currently overgrown with grass and weeds, and as such is unusable in its current state.		<b>Shropshire Council RefRef UM270722:d0154.</b> <b>New Report on FMS 30.07.22</b>	
07.08.22	A51 from Candle Lane to Bridgemere Entrance	Numerous potholes in carriageway, some of which are very dangerous due to size. Most are previous repairs that have		<b>New Report on FMS 07.08.22</b>	
07.08.22	Steps leading from Northlands onto public footpath 0236/22/21	Steps are in a worn and damaged state, and require urgent repair. There have been several instances of people slipping on them, particularly when egressing the path from the field side.		<b>New Report on FMS 07.08.22</b>	
27.10.22	Badly deteriorated footpath leading from the A51 to St Leonards Way Play Area	This footpath is now virtually impassable due to the surface being heavily rutted to one side causing a "bank" on the southern side, so that you are walking in a trench. This Footpath is heavily used by the residents of Woore, and is unusable for mothers with prams and buggies as well as wheelchair users. This has been steadily deteriorating over the past year. THIS REQUIRES URGENT ATTENTION BEFORE WINTER SETS		<b>New Report on FMS 27.10.22.</b>	<b>Shropshire Council Ref:14098829.</b>
06.03.23	From the Square in Woore to the entrance to Woore School, all of the street lights on the A51 are not working.	Streetlights numbers, 12,13,15 and 15 are not lit. This constitutes a significant safety hazard, due to the proximity of the school, the Woore School and a very busy junction between the A51 and the A525, and requires immediate attention.		<b>New Report 06.03.23</b>	