

Woore Parish Council Fix My Street Log (Update 27.10.22)						
Date Reported	Status	Location	Description	Date Fixed	Notes	Shropshire Council Ref.
11/08/2021		A525 W/B carriageway, opposite the Property known as "The Brambles"	Rocking manhole cover, in danger of collapse. Severn Trent		This cover has previously had the blacktop surrounding it replaced, however the cover was not replaced at the same time! Previously reported to Shropshire Council some 3 months previously. - Updated on FMS 29.09.21- no action	
19/08/2021		A51 in the middle of S/B Lane	Linear pothole, road surface breaking up over approx. 10m length. Previously patched. Also breaking up around MH in carriageway channel.	W/C12.09.22 Partial Fix Only	Previously reported to Shropshire Council some 3 and 6 months previously. Some white paint on carriageway. Update on FMS 16.01.22 -This Pothole is now a significant danger, and is now 150mm deep and presents a significant hazard to the travelling public, and requires immediate attention. It is now over 9 months since this was first reported.	
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway Update on FMS 07.03.21-This gully is on the verge of structural failure, the surround has been completely eroded, and the frame is clanking. It is compounded by the fact that the lane is now been trafficked as a single lane under traffic lights, because of Western Power's works, thus doubling the traffic on it, and it will collapse and that requires New Report. Updated on FMS 04.10.21. No Action as at 06.11.21 reported on FMS.	
06/09/2021		Overgrown Hedge leading to Public Footpath 0236/23/1 at end of Northlands Woore	Hedge needs cutting back		No Action - Updated on FMS 29.10.21 as no action	
30/09/2021		A51 Verge - Steps and Handrail Leading up to Public Footpath 0236/26/1	Steps and handrail in need of repair since the handrail has rotted and steps eroded.		No Action - Update posted on FMS 29.10.21 still no action	
30/09/2021		B5026 Bearstone Road entrance	Loose Public Footpath (0236/33/1) Sign, needs re-affixing to Stile.			
29/10/2021		Several Potholes on Dorrington Lane, Woore	Several potholes been here for months have to nearly go into stream to avoid. Between The white House and the westlands. Dorrington Lane near woore		New Report. Updated on FMS 29.10.21 - No Action Update on FMS 27.10.22 Still no resolution on this issue.	
06/10/2021		A51 S/B carriageway opposite junction with Bearstone Road.	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
07/10/2021		Eastern end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report No Action as at 06.11.21 reported on FMS	
07/10/2021		Middle of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report No Action as at 06.11.21 reported on FMS	
07/10/2021		A525 Edge of E/B carriageway approx. 40m past junction with Beech Avenue	Edge of carriageway breaking up and has developed into a serious linear pothole approx 100x500x100 deep, adjacent to previous repair. Dangerous for cyclists and cars.		New Report No Action as at 06.11.21 reported on FMS 10.12.21 - The deficit as reported has been patched, although other adjacent areas remain unprepared.	
07/10/2021		Public Footpath 236/47/1 through Woore Church Yard	Deterioration of footpath through churchyard is a hazard for pedestrians and need repair. First reported. 10.04.21. Outdoor Recreation gave Ref. No. UM110821:90a81 Route No:0236/47/1		New Report First Reported to SC on 19.04.21	UM110821:90a81
07/10/2021		Public Footpath 0236/23/21 at the entrance from Northlands	Footpath has deteriorated at the entrance to Northlands and is presenting a trip hazard. Outdoor recreation advised the following ref. No. UM110821:1a5c7 Route No: 0236/23/1		New Report First Reported to SC on 11.08.21	UM110821:1a5c7
19/10/2021		Intersection of Public Footpaths 0236/22/1 and 236/23/1 on Eastern Boundary of Fields behind Northlands.	Post requires replacement of Field gate on Footpath 0236/23/1		New Report	
21/10/2021		B5025 Dorrington Lane and Watery Lane Crossroads	At Dorrington lane end where the 5026 leads to Irelands Cross, the constant flooding has still not been addressed and this morning, where most other flood prone sites are clear of water, this junction has a pool 2/3rds of the way across the B Road and round the corner adjacent. Our understanding is that this constantly floods due to the water running down Dorrington Lane out of the ditch and down onto the B5026. The drains are silted up and can't cope with all the water.		New Report - First reported to SC several months ago.	SR-174964-T9K7D9
21/10/2021		Severe Flooding on Bearstone Road	Bearstone Road flooding – issue is broken pipes – SC have visited site and instructed SC drainage works team to perform repairs – 3 month notice required for road closure - awaiting update.		New Report - First reported to SC several months ago. Update 10.12.21 - Shropshire Council advised that their contractor has attended site to deal with this, but couldn't do anything because of the flooding! They are to write again to adjacent landowners ref Ditch cleaning.	
21/10/2021		A525/A51 Junction, Audlem Side.	Badly deteriorated road surface, and erased stop line. Vehicles are encroaching into the A51 carriageway to gain visibility around parked cars in lay-by. The absence of the stop line is very dangerous since there is no guide to the driver to stop. Eroded road surface is danger for vehicles under heavy braking with flooded potholes and the risk of ice forming with the onset on winter.	White lines renewed on an unmatched surface, therefore not complete 08/22	New Report	

21/10/2021	Blocked foot way gully on A525 adjacent to Woore Post Office	Drainage gully at the back of the footpath is blocked, and or possibly the outfall drain. Water is discharging across the footpath, and is causing a dangerous surface for pedestrians. This will be exacerbated by the onset of frosty weather causing ice formation with the associated hazards.		New Report - SC attended site on 12.11.21 and attempted to clear the blockage in the outfall drain. The operatives reported to Andy Morris in Woore Country Stores, they thought that the drain was collapsed as a result of excavation work carried out by ST to install a new meter, since there is new surfacing over the	SR-175797-P3B4L6
16/03/2022	Street. Lamp No 38 on the A51 at Crossways	Street Lamp is continuously illuminated		New Report - Reported by resident on Shropshire portal. Now reported on FMS 25.03.22. Update on FMS 27.10.22 Lamp still burning continuously as it has been for the last 7 months!	14085487
19/03/2022	Footpath Post opposite Bankfoot in Gravenhunger Lane Woore	Post is rooted and snapped off, requires replacement, lying against the hedge.		New Report on FMS 19.03.22	
25/03/2022	Rocking Gully Grid on the A51 Opposite Phenix Rise Pipe Gate.	Gully grating is loose as road surface has collapsed around it. Dangerous to all passing traffic, danger of collapse.		New Report on FMS 25.03.22	
06/04/2022	Gateway and signage Gravenhunger Lane Woore	These signs are looking dilapidated, and overgrown. It needs the vegetation and bushes cutting back, and the signage refurbishing or replacing. This is a very well used pedestrian route, and the signage is there to warn motorists of the speed limit and presence of pedestrians. It was installed by SC as part of the quiet lanes initiative.		New Report on FMS 06.04.22	
08.05.22	A525 Audlem Road on Westbound side of C/way	This manhole has previously had the surround to the ironwork replaced, but is now breaking up again, and there are two significant potholes appearing.		New Report on FMS 08.05.22	
08.05.22	Collapsed gully grid on A51 S/B opposite new Development of two Houses.	Gully grid has subsided by about 100mm, and is in danger of collapse. C/way is sub-standard width and receives full HGV loading in the channel, requires immediate attention.		New Report on FMS 08.05.22	
16.07.22	Demolished bollard on junction of A51 and A5026 at Irelands Cross	Centre Island Bollard has been demolished by vehicular traffic, yet again! The island needs to be re-engineered to allow the passage of large articulated HGV's and large farm tractors towing very large trailers.		New Report on FMS 16.05.22	
17.07.22	40mph repeater sign by Holy Cottage on the A51 S/B	Sign obscured by the hedge.		New Report on FMS 17.07.22	
22.07.22	A51 Adjacent To Flash Farm House	The gullies and the culvert under the A51 to the outfall are blocked with debris. As a result under heavy rainfall the carriageway floods and drains into Flash Farm House, which is lower than the carriageway. This issue has been flagged with SC over a year ago, but no action has been taken, and the situation has only got worse. The property has suffered flood damage on several occasions as a result of this cyclic		New Report on FMS 22.07.22 (reported on SC Highways Portal in April 2021)	
25.07.22	Public ROW sign on Gravenhunger Lane Wooreby Aston Hall	PORW sign destroyed by hedge cutting operation.		New Report on FMS 25.07.22	
30.07.22	Public ROW 0236/26/1 adjacent to Phoenix Rise Development	The ROW 0236/26/1 which runs behind the Phoenix Rise Development is currently overgrown with grass and weeds, and as such is unusable in its current state.		Shropshire Council RefRef UM270722:d0154. New Report on FMS 30.07.22	
07.08.22	A51 from Candle Lane to Bridgemere Entrance	Numerous potholes in carriageway, some of which are very dangerous due to size. Most are previous repairs that have		New Report on FMS 07.08.22	
07.08.22	Steps leading from Northlands onto to public footpath 0236/22/21	Steps are in a worn and damaged state, and require urgent repair. There have been several instances of people slipping on them, particularly when egressing the path from the field side.		New Report on FMS 07.08.22	
27.10.22	Badly deteriorated footpath leading from the A51 to St Leonards Way Play Area	This footpath is now virtually impassable due to the surface being heavily rutted to one side causing a "bank" on the southern side, so that you are walking in a trench. This Footpath is heavily used by the residents of Woore, and is unusable for mothers with prams and buggies as well as wheelchair users. This has been steadily deteriorating over the past year. THIS REQUIRES URGENT ATTENTION BEFORE WINTER SETS		New Report on FMS 27.10.22.	Shropshire Council Ref:14098829.

Date Reported	Status	Location	Description
11/10/2019		Junction of Candle Lane and the A51 Nantwich Road - Blocked Culvert causing Flooding	This Issue was first reported to Shropshire Council 11.10.19 - On Candle Lane at the end nearest to the A51 Nantwich Road the culvert is overflowing with water, due possibly to the drain than runs under the road blocked which would allow the water to run into the field. There is also concern of two vehicles passing on this lane that due to the culvert obscured by tall grass that a vehicle may end up in the culvert.....does this
08/03/2020		Junction of A51 and A5026	Direction sign severely damaged by a collision with an HGV
03/08/2021		A51 at junction of Candle Lane, S/B side verge	30mph sign is obscured by overgrown by vegetation
11/08/2021		Bellmouth to entrance to Ash Mount off A525	Multiple Severn Trent Covers (4) have large potholed areas around them, total area is 1.2 sum eroded to a depth of 30-40mm. Serious trip hazard, as it hit is in the line of the pedestrian crossing of the junction.
11/08/2021		A525 on E/B Footpath adjacent to "The Meads"	Double BT Manhole Cover in footway, Covers are not seated properly after removal maintenance, and presents a trip hazard. There is a 15mm up-stand
11/08/2021		A525 E/B Carriageway opposite the entrance to Swan Farm Lane	500x500x120deep pothole in carriageway channel area.
19/08/2021		A51 N/B opposite entrance to Betty's lane	Previously repaired Manhole surround, (2020), breaking up in carriageway with a significant pothole developing. Severn Trent
19/08/2021		A525 W/B carriageway opposite Red Lion Farm	Rocking manhole cover, in danger of collapse. Severn Trent
19/08/2021		A525 W/B carriageway opposite Property known as "Resthaven" the entrance with a 5 bar gate.	Rocking manhole cover, in danger of collapse. Severn Trent
19/08/2021		A51 London Road S/B carriageway. Approx. 100 m South of entrance to property known as Warren Heights	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Carriageway breaking up around gulley causing pothole in channel Very Dangerous
06/09/2021		A525 W/B verge opposite TT Pumps Premises	Collapsed gullies in the verge, very dangerous
06/10/2021		B5026 Bearstone Road S/B carriageway opposite Dorrington Lane Crossroads.	Double BT Manhole collapsing, roads surface eroded away from frame.

07/10/2021		Western end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding. This was previously repaired earlier this year, and has failed again.
26/10/2021		Inspection cover On Lamppost Ref:8146-2 lying on pavement, electrics exposed On Audlem Road	Lamppost Inspection cover lying on the pavement with exposed electrics on the Eastbound pavement of A525 Audlem Road in Woore Village. This is a danger to the public, and requires Immediate attention.
28/10/2021		Streetlight - very bright light shining onto property	The streetlight outside the property referenced below has had the bulb/head replaced fairly recently and since then, the light is significantly brighter than the others and is also now shining directly onto the property opposite (Elmhurst Lay, Woore, CW3 9RQ). The light seems brighter than an average streetlight bulb. It is causing an issue for the residents of that property. <u>Please can it be addressed</u>
12/11/2021		Street Lamp out on Westbound side of the A525 adjacent to Buckley Hall.	Street Lamp requires replacement
11/12/2021		Pothole at the entrance to Grove Crescent	This pothole started off as a minor hole and has now developed over the past month into significant pothole some 300x300 and 100deep. It is a danger to Both vehicular traffic and a trip hazard for the many pedestrian using this crossing point.
10.07.21		A525 Edge of W/B carriageway approx. 35 past junction with Beech Avenue	Surround to double BT manhole cover breaking up, causing a pothole that is deteriorating. This is a previously repaired manhole.
16/03/2022		30 mph sign in verge on approach to Woore Village from Audlem	Sign post is snapped off and laying in the verge.