

Date Reported	Status	Location	Description	Date Fixed	Notes	Shropshire Council Ref.												
11/10/2019		Junction of Candle Lane and the A51 Nantwich Road - Blocked Culvert causing Flooding	This Issue was first reported to Shropshire Council 11.10.19 - On Candle Lane at the end nearest to the A51 Nantwich Road the culvert is overflowing with water, due possibly to the drain than runs under the road blocked which would allow the water to run into the field. There is also concern of two vehicles passing on this lane that due to the culvert obscured by tall grass that a vehicle may end up in the culvert.....does Direction sign severely damaged by a collision with an HGV	06.04.22	Update 16.12.21 Reported on FMS - The PC are not aware of any jetting taking place, also at the time of Reporting the Highways Technician advised installing bollards to inform road users. Since 2019 there have been two white vans gone into the culvert that I know of, noticed again yesterday that the road is flooding again! Update 06.04.22 SC updated FMS to say the issue had													
08/03/2020		Junction of A51 and A5026		28/10/2021	This sign has been in a damaged state for 2 years, aspire repeated requested requests to Shropshire Council to repair it. Fixed on 19/03/22 some years after being reported !!!!													
03/08/2021		A51 at junction of Candle Lane, S/B side verge	30mph sign is obscured by overgrown by vegetation	28/10/2021	Update 01.09.21 reported on FMS - No Action by SC. Problem cleared by annual hedge cutting FMS updated.													
11/08/2021		Bellmouth to entrance to Ash Mount off A525	Multiple Severn Trent Covers (4)have large potholed areas around them, total area is 1.2 sum eroded to a depth of 30-40mm. Serious trip hazard, as it hit isin the line of the pedestrian crossing of the junction.	28/10/2021	Previously reported to Shropshire Council some 3 months previously - Repaired 28.02.21 full patch													
11/08/2021		A525 on E/B Footpath adjacent to "The Meads"	Double BT Manhole Cover in footway, Covers are not seated properly after removal maintenance, and presents a trip hazard. There is a 15mm up-stand	28.02.22	This was originally reported on the Shropshire Council Portal some months previously. Still no action at 06.10.21! Cover marked in white paint with S81 - Updated on FMS 29.10.21 - No Action-Fixed 28.02.22 by BT Emergency	New Report - Update 16.12.21 Reported on FMS The street lamp has still not been repaired by Shropshire Council . Further update on16.01.2022 on FMS - still not repaired												
19/08/2021		A51 N/B opposite entrance to Betty's lane	Previously repaired Manhole surround, (2020), breaking up in carriageway with a significant pothole developing. Severn Trent	17/10/2021	Repaired by ST on17.10.21													
19/08/2021		A525 W/B carriageway opposite Red Lion Farm	Rocking manhole cover, in danger of collapse. Severn Trent	30/09/2021	Previously reported 3 months previous to Shropshire County Council. Now fixed.													
19/08/2021		A525 W/B carriageway opposite Property known as "Resthaven" the entrance with a 5 bar gate.	Rocking manhole cover, in danger of collapse. Severn Trent	30/09/2021	Previously reported 3 months previous to Shropshire County Council. Repaired by ST 17.10.21													
19/08/2021		A51 London Road S/B carriageway. Approx. 100 m South of entrance to property known as Warren Heights	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	17/10/2021	Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway. Repaired by ST 17.10.21													
06/09/2021		A525 W/B verge opposite TT Pumps Premises	Collapsed gullies in the verge, very dangerous	30/09/2021	Temporary cones placed after 5 days, repairs now carried out.													
06/10/2021		B5026 Bearstone Road S/B carriageway opposite Dorrington Lane Crossroads.	Double BT Manhole collapsing, roads surface eroded away from frame.	23.10.22	Been in that condition for over 6 weeks	Fixed on 23.10.22 by BT, FMS Updated												
26/10/2021		Inspection cover On Lamppost Ref:8146-2 lying on pavement, electric exposed On Audlem Road	Lamppost Inspection cover lying on the pavement with exposed electric on the Eastbound pavement of A525 Audlem Road in Woore Village. This is a danger to the public, and requires immediate attention.	28/10/2021	New Report - Repaired	SR-175453-Z1W3V4												
28/10/2021		Streetlight - very bright light shining onto property	The streetlight outside the property referenced below has had the bulb/head replaced fairly recently and since then, the light it significantly brighter than the others and is also now shining directly onto the property opposite (Elmhurst Lay, Woore, CW3 9RQ). The light seems brighter than an average streetlight bulb. It is causing an issue for the residents of that property. Please can it be addressed.	06.11.21	New Report. The Lamp has been replaced with an LED Unit that does not sit within a cover. All SC Lamps are being replaced with LED Units as they fail. Issue to be taken up with SC by the Resident direct, since it is policy issue.	SR175833-B5S4P9												
12/11/2021		Street Lamp out on Westbound side of the A525 adjacent to Buckley Hall.	Street Lamp requires replacement	17.03.22	Repaired by SC, head and lamp replaced with LED unit.	New Report - Update 16.12.21 Reported on FMS The street lamp has still not been repaired by Shropshire Council . Further update on16.01.2022 on FMS - still not repaired by SC. 17.03.22 - Repaired FMS updated.												
10.07.21		A525 Edge of W/B carriageway approx. 35 past junction with Beech Avenue	Surround to double BT manhole cover breaking up, causing a pothole that is deteriorating. This is a previously repaired manhole.	04.03.22	Repaired on 04.03.22, surfacing was dressed into soil on the verge side, so will probably fail soon again!	New Report No Action as at 06.11.21 reported on FMS												
16/03/2022		Street. Lamp No 38 on the A51 at Crossways	Street Lamp is continuously illuminated	04.03.22	New Report - Reported by resident on Shropshire portal. Now reported on FMS 25.03.22. - 31.03.22 Lamp appears to be working normally now.													
16/03/2022		30 mph sign in verge on approach to Woore Village from Audlem	Sign post is snapped off and laying in the verge.	04.03.22	New Report Update 04.04.21 - Sign pole replaced and signs re-erected on pole by Shropshire Council													